

PROCESS AND APPARATUS FOR THE HYDROGENATION OF
POLYMERS UNDER SUPERCRITICAL CONDITIONS

By William M. Cole
Sheet 1 of 4 Sheets

File No. P01029US1A

Express Mail Label No. EL726089653US




FIG. 1

PROCESS AND APPARATUS FOR THE HYDROGENATION OF
POLYMERS UNDER SUPERCRITICAL CONDITIONS

By William M. Cole
Sheet 2 of 4 Sheets

File No. P01029US1A

Express Mail Label No. EL726089653US





FIG. 2

Figure 3 - Critical Properties of Mixtures of Hydrogen and n-Hexane






FIG. 4